



TC-25 -07

REQUEST FOR TRAFFIC CONTROL INVESTIGATION/IMPROVEMENT

TODAY'S DATE: 6/11/25 DATE PROBLEM NOTED: _____

APPLICANT'S NAME [REDACTED] TIME OF DAY: _____ AM/PM

ADDRESS [REDACTED] CONTRIBUTING FACTORS: (CHECK ONE):

- () Weather (☒) Road Surface Condition
() Hedges/Trees () Street Lighting
() Others _____

TELEPHONE: (H [REDACTED])
(W) _____

LOCATION OF PROBLEM: Speed bump outside 1444 Marylhurst Dr

REQUEST: Modify speed bump to inhibit speeding

REASON REQUESTED The current speed bump does not require cars to reduce speed. Other speed bumps in the neighborhood are able to accomplish this. This road has a significant slope making it easier to speed.

ADDITIONAL COMMENTS: In the past speed monitors were placed at the corner of Sylvan Way and Marylhurst Dr but would accumulate data from slow cars turning at that intersection. If a speed monitor is to be used in proving the speed bump does not reduce driver speed please feel free to place it outside of my house at [REDACTED] for potentially more accurate data collection.

Thank you for completing this informational form. Your input is an important part of analyzing the above described problem. City Staff will review your request and conduct the necessary investigations. Please use the back of this form for a sketch or diagram as appropriate.

Please return to: Attn: Public Works Department
City of West Linn
4100 Norfolk Street
West Linn, OR 97068

Phone: (503) 656-6081
e-mail: streets@westlinnoregon.gov