

TC- 25 -	
-----------------	--

REQUEST FOR TRAFFIC CONTROL INVESTIGATION/IMPROVEMENT

TODAY'S DATE: Oct 3rd, 2025	DATE PROBLEM NOTED: Oct 3rd, 2025		
APPLICANT'S NAME.	TIME OF DAY: 5:00 PM	AM/PM	
ADDRES	CONTRIBUTING FACTORS: (CHECK ONE):		
TELEPHONE: (A)	() Weather () Road Surface Cond () Hedges/Trees () Street Lighting () Others	ition	
(W)			
LOCATION OF PROBLEM: The intersection of Willan	mette Falls Dr and W A St		
REQUEST: Please consider adding a curved mirror	on the bend in the road on Willamette Falls Dr where peop	le	
turn left onto W A St, on the side of the road with the	ne apartment building.		
REASON REQUESTED During rush hour, both lanes	of Willamette Falls Dr are slow moving and block visibility f	or cars who	
	ch safer if the driver had a mirror to check that no cars are c		
Willamette Falls. I have seen many close calls whe	en people are turning here.		
ADDITIONAL COMMENTS:		_	
ADDITIONAL COMMENTS.			
	form. Your input is an important part of analyzing to request and conduct the necessary investigations. as appropriate.		

Phone: (503) 656-6081

e-mail: streets@westlinnoregon.gov

Attn: Public Works Department Please return to:

City of West Linn 4100 Norfolk Street West Linn, OR 97068