

## REQUEST FOR TRAFFIC CONTROL INVESTIGATION/IMPROVEMENT

TODAY'S DATE: December 30, 2025 DATE PROBLEM NOTED: Ongoing since Ostman stop sign

APPLICANT'S NAME: [REDACTED] TIME OF DAY: Esp. afternoon traffic back up AM/PM

ADDRESS: \_\_\_\_\_ CONTRIBUTING FACTORS: (CHECK ONE): \_\_\_\_\_

TELEPHONE: (H) [REDACTED]  Weather  Road Surface Condition  
 Hedges/Trees  Street Lighting  
 Others

TELEPHONE: (H) \_\_\_\_\_ (O) \_\_\_\_\_ (C) \_\_\_\_\_ (S) \_\_\_\_\_ (P) \_\_\_\_\_ (G) \_\_\_\_\_ ( ) Others \_\_\_\_\_

(W) \_\_\_\_\_

**LOCATION OF PROBLEM:** West driveway entrance of residential property at this address.

REQUEST: Installation of already purchased curved mirror onto the street light pole across WFD from west driveway.

REASON REQUESTED The steep driveway approach onto Willamette Falls Drive from residence is compounded by the daily presence of backed up traffic which blocks visibility when turning left or west, out of driveway onto WFD.

This is further exacerbated by the tendency of w/b drivers to inevitably accelerate after waiting at the Ostman stop.

ADDITIONAL COMMENTS: A curved mirror installed on the street light pole across WFD from residence driveway would improve site distance and better equip vehicles to time their approach onto WFD avoiding collisions and improving safety for all.

*Thank you for completing this informational form. Your input is an important part of analyzing the above described problem. City Staff will review your request and conduct the necessary investigations. Please use the back of this form for a sketch or diagram as appropriate.*

*Please return to: Attn: Public Works Department  
City of West Linn  
4100 Norfolk Street  
West Linn, OR 97068*

Phone: (503) 656-6081  
e-mail: [streets@westlinnoregon.gov](mailto:streets@westlinnoregon.gov)