



TC- 26 - 05

REQUEST FOR TRAFFIC CONTROL INVESTIGATION/IMPROVEMENT

TODAY'S DATE: 2/24/2026 DATE PROBLEM NOTED: 2/19/2026

APPLICANT'S NAME: [REDACTED] TIME OF DAY: 3:30 PM AM/PM

ADDRESS: [REDACTED] CONTRIBUTING FACTORS: (CHECK ONE):

[REDACTED] ☐ Weather ☐ Road Surface Condition

☐ Hedges/Trees ☐ Street Lighting

TELEPHONE: (H) [REDACTED] ☐ Others _____

(W) _____

LOCATION OF PROBLEM: Corner of Willamette Falls Drive and Epperly Way

REQUEST: Remediate the curb configuration at this intersection to reduce the crash risk for cyclists travelling through this intersection.

REASON REQUESTED There is a raised curb directly in the line of travel for a bicyclist traveling downhill on the bike path through this intersection.

This presents a safety issue that can be mitigated by removing the curb and/or painting stripes on the ground that guide cyclists
away from the curb.

ADDITIONAL COMMENTS: Please see a detailed narrative and pictures describing the problem at

<https://user.govoutreach.com/westlinncityor/case.php?id=10280134&access=6363346532626530>

Thank you for completing this informational form. Your input is an important part of analyzing the above described problem. City Staff will review your request and conduct the necessary investigations. Please use the back of this form for a sketch or diagram as appropriate.

*Please return to: Attn: Public Works Department
City of West Linn
4100 Norfolk Street
West Linn, OR 97068*

*Phone: (503) 656-6081
e-mail: streets@westlinnoregon.gov*