

TO	
I.C.	2.5

REQUEST FOR TRAFFIC CONTROL INVESTIGATION/IMPROVEMENT

TODAY'S DATE: 3-19-24	DATE PROBLEM NO	OBLEM NOTED: 2019-current	
APPLICANT'S NAME	TIME OF DAY: Sch	TIME OF DAY: School hours	
ADDRESS:	CONTRIBUTING FACTORS: [CHECK ONE):		
TELEPHONE: (H)	O Weather O Hedges/Trees (0) Others, https://doi.org/10.1009/10.000	(0) Road Surface Condition (0) Street Lighting 1000 cover one may k class; till other may	
LOCATION OF PROBLEM: Crosswalk on Santa Anita Drive	at intersection of Horton Road an	d Churchill Downs Drive.	
REQUEST: Add flashing lights at the location. Exist	ting crossing flags have pro-	ven to be ineffective.	
REASON REQUESTED We have had numerous issues of a Aggressive drivers are unaware of us in the crosswalk until		est totaliste for each company is continue	
honk at us.			
ADDITIONAL COMMENTS: We have reported this to	the Haverhill Homeowners	Association, and they have	
acknowledged that other neighbors have als	so had issues.		
Thank you for completing this informational forn described problem. City Staff will review your require hack of this form for a sketch or diagram as a	quest and conduct the neces		

Please return to: Attn: Jeff Randall

Attn: Jeff Randall Phone: (503) 742-6091
Public Works Department e-mail: jrandall@westlinnoregon.gov

City of West Linn 4100 Norfolk Street West Linn, OR 97068