



## REQUEST FOR TRAFFIC CONTROL INVESTIGATION/IMPROVEMENT

TODAY'S DATE: 17 November 2025 DATE PROBLEM NOTED: Constantly

APPLICANT'S NAME: [REDACTED] TIME OF DAY: 2:30 TO ABOUT 6:30 PM

ADDRESS: [REDACTED] CONTRIBUTING FACTORS: (CHECK ONE):

Weather  Road Surface Condition

Hedges/Trees  Street Lighting

TELEPHONE: (H) [REDACTED]  Others SPEEDING, UNIMPROVED ROAD, NO SIGNAGE  
(W) [REDACTED]

LOCATION OF PROBLEM: UPPER MIDHILL DRIVE - FROM ARBOR TO MARYLHURST DRIVE

SEE MAP ON ATTACHED PAGE 2

REQUEST: REQUESTING SPEED LIMIT SIGNS BE INSTALLED - 15 MPH PER ODOT GUIDELINES FOR UNIMPROVED ROADS AND ALLEYS. ALSO REQUEST POLICE DEPARTMENT ENFORCE SPEED LIMIT IN THIS AREA.

REASON REQUESTED DAILY, AFTERNOON RUSH HOUR TRAFFIC BOTTLENECKS ON HWY 43. FOLKS ARE IN SUCH A HURRY, THEY BYPASS PART OF THE CONGESTION BY DIVERTING UP ARBOR, DOWN UPPER MIDHILL AND THEN DOWN MARYLHURST TO THE LIGHT AT HWY 43. MULTIPLE VEHICLES ARE DRIVING IN EXCESS OF DOUBLE THE SPEED LIMIT. FOLKS ARE WALKING THEIR KIDS IN STROLLERS, THEIR DOGS AND KIDS ON BIKES

ADDITIONAL COMMENTS: THIS ISSUE HAS ALWAYS BEEN SINCE I MOVED HERE ALMOST 30 YEARS AGO. SINCE THE WATER MAIN REPLACEMENT AND REPAVING, THE ROAD SURFACE IS SMOOTHER. THIS SEEMS TO HAVE CAUSED EVEN MORE TRAFFIC TO TRANSITION THRU AT MUCH FASTER SPEEDS.

*Thank you for completing this informational form. Your input is an important part of analyzing the above described problem. City Staff will review your request and conduct the necessary investigations. Please use the back of this form for a sketch or diagram as appropriate.*

Please return to: Attn: Public Works Department  
City of West Linn  
4100 Norfolk Street  
West Linn, OR 97068

Phone: (503) 656-6081  
e-mail: [streets@westlinnoregon.gov](mailto:streets@westlinnoregon.gov)

