



TC- 26 - 03

REQUEST FOR TRAFFIC CONTROL INVESTIGATION/IMPROVEMENT

TODAY'S DATE: 02/02/26 DATE PROBLEM NOTED: 02/02/26
APPLICANT'S NAME: [REDACTED] TIME OF DAY: 8:45 AM AM/PM
ADDRESS: [REDACTED] CONTRIBUTING FACTORS: (CHECK ONE):
[REDACTED] ☐ Weather ☐ Road Surface Condition
☐ Hedges/Trees ☐ Street Lighting
TELEPHONE: (H) [REDACTED] ☐ Others _____
(W) _____

LOCATION OF PROBLEM: MARYLHURST DRIVE, BETWEEN THE INTERSECTIONS OF VIEW DRIVE (EAST)
AND VIEW DRIVE (WEST)

****SEE MAP OF INTERSECTIONS MENTIONED, AS WELL AS SCHOOL BUS STOPS ****

REQUEST: 1) SIGNS AND/OR FLASHING BEACON INDICATING SCHOOL BUS STOPS AND PEDESTRIANS
IN THE ROADWAY ALONG MARYLHURST BETWEEN THE VIEW DRIVE/MARYLHURST INTERSECTIONS
2) STOP SIGN ON MARYLHURST AT VIEW DRIVE (EAST) INTERSECTION

REASON REQUESTED SPEED IS AN ONGOING ISSUE, ESPECIALLY DOWNHILL SPEED AFTER DRIVERS PASS
VIEW DRIVE (EAST). THERE ARE THREE SCHOOL BUS STOPS ALONG MARYLHURST WHICH THE NEIGHBORHOOD
KIDS WALK ALONG TO GET TO THEIR STOP. THIS MORNING 2/2/26, SEVERAL DRIVERS DID NOT ALLOW THE RIGHT
OF WAY TO THE STUDENTS WALKING ALONG THE VERY NARROW SHOULDER ON MARYLHURST.

ADDITIONAL COMMENTS: WE DON'T WANT TO RISK A FATALITY OR BODILY INJURY BECAUSE OF THE LACK
OF CAUTIONARY STREET SIGNS OR INDICATORS OF STREET TRAFFIC.

Thank you for completing this informational form. Your input is an important part of analyzing the above described problem. City Staff will review your request and conduct the necessary investigations. Please use the back of this form for a sketch or diagram as appropriate.

Please return to: Attn: Public Works Department
City of West Linn
4100 Norfolk Street
West Linn, OR 97068

Phone: (503) 656-6081
e-mail: streets@westlinnoregon.gov