



TC- 26 - 06

REQUEST FOR TRAFFIC CONTROL INVESTIGATION/IMPROVEMENT

TODAY'S DATE: 03/02/2026 DATE PROBLEM NOTED: 01/14/26

APPLICANT'S NAME: [REDACTED] TIME OF DAY: 7:15 AM AM/PM

ADDRESS: [REDACTED] CONTRIBUTING FACTORS: (CHECK ONE):

[REDACTED] () Weather () Road Surface Condition

[REDACTED] () Hedges/Trees () Street Lighting

TELEPHONE: (H) [REDACTED] () Others _____

(W) _____

LOCATION OF PROBLEM: The section of Bland Circle between Weatherhill and Eleanor.

REQUEST: Place speed bumps or revert back to one way.

REASON REQUESTED The road is very narrow with barely enough room for vehicles going opposite directions to pass safely. It is especially difficult with school buses and large construction vehicles. Cars are often going 30 to 40 mph using this "short cut" and it is dangerous especially for pedestrians. At one point the city made it 1 way because of the problems, but eventually reverted to 2 way traffic and now there is significantly more traffic on it.

ADDITIONAL COMMENTS: On 1/13/26 I witnessed a gentleman and his dog have to jump off the road in order to avoid being hit by two cars going in opposite directions and speeding. Many of us (including kids) walk that section of road daily and see this type of issue every week, if not every day. Please help.

Thank you for completing this informational form. Your input is an important part of analyzing the above described problem. City Staff will review your request and conduct the necessary investigations. Please use the back of this form for a sketch or diagram as appropriate.

Please return to: Attn: Public Works Department
City of West Linn
4100 Norfolk Street
West Linn, OR 97068

Phone: (503) 656-6081
e-mail: streets@westlinnoregon.gov