


Arran Court Water Main Break

Recently, a four-inch ductile iron pipe installed in 1987 broke on Arran Court. This pipe was incorrectly installed, and is also the wrong class of pipe (wall thickness) commonly used for non-pressure collection. This break was fixed by West Linn Water crews.



Source URL (retrieved on 2012-05-10 13:09):

<http://westlinnoregon.gov/publicworks/arran-court-water-main-break>