


Owner West Linn	Customer West Linn	Upstream MH 3a-76	Downstream MH 3a-75	Date 10-Dec-2009	Time 9:57 AM
---------------------------	------------------------------	-----------------------------	-------------------------------	----------------------------	------------------------


Surveyor bpainter	Street 690 marlhust dr	City West Linn	Weather Dry
-----------------------------	----------------------------------	--------------------------	-----------------------

Size 8	Material Reinforced Concrete Pipe	Sewer Use Sanitary	Purpose F	Length
------------------	---	------------------------------	---------------------	---------------


Comments	Pre-Cleaning Jetting	TV Length 351.2
-----------------	--------------------------------	---------------------------



Owner West Linn	Customer West Linn	Upstream MH 3a-77	Downstream MH 3a-76	Date 10-Dec-2009	Time 9:44 AM
Surveyor bpainter	Street 615 marlhust dr		City West Linn	Weather Dry	
Size 8	Material Reinforced Concrete Pipe	Sewer Use Sanitary	Purpose F	Length	
Comments				Pre-Cleaning Jetting	TV Length 217.7



Owner West Linn	Customer West Linn	Upstream MH 3a-78	Downstream MH 3a-77	Date 10-Dec-2009	Time 9:31 AM
Surveyor bpainter	Street 615 marlhust dr		City West Linn	Weather Dry	
Size 8	Material Reinforced Concrete Pipe	Sewer Use Sanitary	Purpose F	Length	
Comments			Pre-Cleaning Jetting	TV Length 157.6	





CITY OF West Linn

Owner West Linn	Customer West Linn	Upstream MH 3a-79	Downstream MH 3a-78	Date 08-Dec-2009	Time 3:39 PM
Surveyor bpainter	Street 521 marylhurst dr		City West Linn	Weather Dry	
Size 8	Material Reinforced Concrete Pipe	Sewer Use Sanitary	Purpose F	Length	
Comments				Pre-Cleaning Jetting	TV Length 261.9

