



APPEAL of Conditional Use Permit

Willamette Neighborhood Association 10/04/2021











CDC, Chap 60 criteria for CUP




West Linn Comprehensive Plan, Goals 7 & 12

Inadequate Acreage

Unsuitable site for extra large school





^{*} Building capacity

^{**17} developable acres for 850 students, but only 15.5 acres developing

Inadequate Acreage

Repercussions



School Facilities


		Athey Creek	Proposed School
Baseball fields	•	5	X
Tennis Courts		4	X
Basketball		4	3
Soccer fields		3	X
Track & Field	Ż	1	1


NOT Centrally Located

Unsuitable site

most outside of

Willamette area





Inadequate WALKING infrastructure



Lack of sidewalks, steep hills on streets connecting to Safe Routes






FIGURE 10: SCHOOL SAFE ROUTES TO SCHOOL AND WALKING BOUNDARY

Inadequate DRIVING infrastructure

Proposed school will be located between Minor Arterial and Local Streets





Intersections are required to meet the City of West Linn standard for an unsignalized intersections to operate at or below LOS D. (Highway Capacity Manual, 6th Edition, Transportation Research Board, 2017.)

Where will parents go?

Inadequate PARENT access points




Safety & Congestion on Bridge Roundabout

DKS estimates midday peak hour of at least 7 vehicles queue extending on to bridge



WFD Safety & Emergency Access

No place for cars to go due to narrow road and no shoulder




Residents Trapped

Limited access for Emergency vehicles

Life or death









Unofficial Parent Drop Offs

Repercussions of Inadequate Infrastructure & Impractical Planning








Per Application, WFD & Dollar St. to be connected for Public Use



OPEN

Per Application, WFD & Dollar St. to be connected for Public Use



OPEN


Excessive new trips on local street



+200-300/per day NON-school, non-local traffic


Fails to protect neighborhoods from excessive through traffic

Per Condition 10, Extension closed to Public





Per Condition 10, Extension closed to Public









Fails to meet the minimum standard of safety



Repercussions of Inadequate Infrastructure & Impractical Planning



OPEN







