




Problem Location:

Willamette Falls Drive & Broadway Street

Description

the crosswalk at this location has become very dangerous. At this location there are 2 lanes of traffic in each direction. The roundabout has created an issue where drivers are trying to merge in with drivers also headed in the west direction-toward the high school. When merging they are focused on the traffic to their left. However while merging there may be pedestrians in the crosswalk ahead of them. I have now had 4 incidents in this intersection of near misses, where I had to run out of the way of a speeding car, or drivers having to slam on their brakes. One incident I was holding my 4 year old grandson. The crosswalk is also very dangerous when traffic is backed up on Willamette Falls Drive. Pedestrians must weave through backed up cars, and often are hidden from cars coming the opposite direction. This is very dangerous. The Bolton neighborhood and high school student use this intersection very frequently. A push button and signage with blinking light system for pedestrians is needed, before a serious accident takes place. Thank you for considering this important issue.

[View Request](#)

How did we do?

Fill out a short survey to help us improve.

[Fill Out Survey](#)

This message is intended for the sole use of the addressee, and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If you are not the addressee you are hereby notified that you may not use, copy, disclose, or distribute to anyone the message or any information contained in the message. If you have received this message in error, please immediately advise the sender by reply email and delete this message.