



TC-26 - 24

REQUEST FOR TRAFFIC CONTROL INVESTIGATION/IMPROVEMENT

TODAY'S DATE: 07/06/2026 DATE PROBLEM NOTED: 07/06/2026
APPLICANT'S NAME: [REDACTED] TIME OF DAY: All AM/PM
ADDRESS: [REDACTED] CONTRIBUTING FACTORS: (CHECK ONE):
() Weather () Road Surface Condition
() Hedges/Trees () Street Lighting
TELEPHONE: (H) [REDACTED] () Others _____
(W) _____

LOCATION OF PROBLEM: Intersection of Willamette Falls Drive and Ostman.

REQUEST: Addition of crosswalk and flashing crosswalk sign for pedestrians crossing Willamette Falls Drive.

REASON REQUESTED Create a safe crossing for children crossing Willamette Falls Drive on their way to and from Athey Creek Middle School

As traffic increases during peak travel times and commuters routinely roll through the 4-way without coming to a complete stop, our
hope is to ensure safe access to the school and avoid a preventable accident.

ADDITIONAL COMMENTS: The nearest crosswalks are either downtown Willamette or the entrance to Fields Bridge.

There is no continuous sidewalk or safe access to either of these crosswalks on the south side of Willamette Falls Drive.

Thank you for completing this informational form. Your input is an important part of analyzing the above described problem. City Staff will review your request and conduct the necessary investigations. Please use the back of this form for a sketch or diagram as appropriate.

*Please return to: Attn: Public Works Department
City of West Linn
4100 Norfolk Street
West Linn, OR 97068*

*Phone: (503) 656-6081
e-mail: streets@westlinnoregon.gov*